INSTALLATION AND SERVICE INSTRUCTIONS

REFRIGERATOR MODELS: BM48, BM62, BM68, BM72, BM87, BM96, BM48S, BM62S, BM68S, BM72S, BM84S, BM87S, BM90S, BM96S

FOR YOUR SAFETY

THESE UNITS ARE EQUIPPED WITH A THREE-PRONG ELECTRICAL PLUG. THIS THREE-PRONG PLUG IS PART OF A SYSTEM THAT WILL PROTECT YOU IF SOMETHING GOES WRONG WITH THE ELECTRICAL WIRING IN THE UNIT. BE SURE THE THREE-PRONG PLUG IS PLUGGED INTO A MATCHING THREE-PRONG SOCKET. **DO NOT** CUT OR BREAK OFF THE THIRD PRONG IN THIS PLUG, OR THE PROTECTOR SYSTEM WILL NOT WORK.

REFRIGERATOR MAINTENANCE

- 1. Vacuum flour and or dust from the condenser (located in front of the condensing unit) a minimum of one time per week or as often as necessary to insure proper circulation of air.
- 2. If the fan motor in the evaporator (located inside the refrigerator) does not turn or makes a noise, shut refrigerator off to allow time to defrost the possible ice build up on the coils.

CLEANING TIPS

- 1. Spilled food must be removed immediately. Do not allow grease and stains to accumulate on surfaces.
- 2. Apply a non-abrasive cleaning solution to all surfaces. Pay particular attention to corners and other areas that might collect food particles.
- 3. Rinse with warm water and dry.

NOTE

- ◆ In Pizza Prep Tables and open top Refrigerators, all pans must be installed at all times.
- ♦ In all Refrigerators and Freezers, door gaskets must be checked for splits or improper seals. This would allow warm outside air inside the unit causing condensation to collect on the evaporator coil.



FIRST YEAR WARRANTY

ALL PARTS ARE WARRANTED FOR A PERIOD OF ONE YEAR OR 13 MONTHS FROM SHIPPING AGAINST MANUFACTURERS DEFECTS IN MATERIAL AND WORKMANSHIP UNDER NORMAL USE, AND APPLIES ONLY TO THE ORIGINAL PURCHASER PROVIDING THAT THE EQUIPMENT IS PROPERLY INSTALLED, ADJUSTED, OPERATED AND MAINTAINED AND ALSO, THE EQUIPMENT HAS NOT BEEN ACCIDENTALLY OR INTENTIONALLY DAMAGED, ALTERED OR MISUSED. WITHIN THE FIRST YEAR, THE COMPRESSOR IS WARRANTED BY TECUMSEH PRODUCTS AND MUST BE RETURNED TO A WHOLESALER BY THE SERVICE COMPANY FOR PROPER CREDIT.

- ♦ ALL OTHER PARTS MUST BE RETURNED TO MARSAL & SONS, INC. BEFORE CREDIT IS ISSUED.
- ♦ ADJUSTMENTS ARE NOT COVERED UNDER WARRANTY.
- ♦ THE USE OF CAUSTIC CLEANERS WILL VOID THE WARRANTY.

ADDITIONAL 4 YEAR WARRANTY

THE NEXT FOUR YEARS, THE COMPRESSOR IS WARRANTED BY MARSAL & SONS, INC. THE DEFECTIVE COMPRESSOR MUST BE RETURNED, FREIGHT PREPAID, TO MARSAL & SONS, INC. 175 EAST HOFFMAN AVENUE., LINDENHURST, NY 11757, THE REPLACEMENT COMPRESSOR WILL BE SHIPPED FREIGHT COLLECT.

***** WARRANTY LABOR WORK WILL ONLY BE PAID ON A REASONABLE NORMAL BUSINESS HOUR RATE. ANY OVERTIME CHARGES IS NOT THE RESPONSIBILITY OF THE MANUFACTURER. ALL TRAVEL CHARGES ARE LIMITED TO 60 MILES OR LESS.